

Water Connections

Is the service line HDPE?



ALLIANCE FOR
pepipe

Yes

**Are you connecting to
PE Main?**

Yes

**Do you want
to use fusion?**


Yes

Saddle




Electrofusion

Mechanical strap saddle



Use threaded transition fitting to connect to corporation stop


Choose transition material: stainless, brass, copper epoxy coated




Saddle



Electrofusion



Mechanical strap saddle



A line drawing of a mechanical strap saddle. It features a central rectangular body with a threaded rod passing through it. Two curved, hook-like straps are attached to the sides of the central body, each ending in a small rectangular pad. The entire device is shown from a top-down perspective.

No

**Are you connecting to
PE Main?**

Yes

**Do you want
to use fusion?**

Yes

No

Contact that industry for tapping requirements

